

4

3

2

1

THIS DRAWING IS UNPUBLISHED.	RELEASED FOR PUBLICATION	LOC	DIST	REVISIONS			
© COPYRIGHT	ALL RIGHTS RESERVED.						
				P	LTR	DESCRIPTION	DATE
						A1 ECR-14-002235	17FEB2014
							GK HMR

REPLACED BY OCEAN STYLE APPLICATOR PART NUMBER 2151899-1

FOR REPLACEMENT PARTS FOR APPLICATOR 1528933
REFER TO ADDITIONAL PAGE(S). SPARE PARTS KIT (IF LISTED)
WILL REMAIN AVAILABLE.

THE REPLACEMENT OCEAN STYLE APPLICATOR HAS THE
SAME TERMINATOR/PRESS INTERFACE AS APPLICATOR
1528933

THIS DRAWING IS A CONTROLLED DOCUMENT.		DWN GOPALAKRISHNA HV		TE Connectivity	
DIMENSIONS:		CHK RAGHAVENDRA			
		APVD RAGHAVENDRA			
TOLERANCES UNLESS OTHERWISE SPECIFIED:		PRODUCT SPEC			
0 PLC ±		APPLICATION SPEC			
1 PLC ±					
2 PLC ±					
3 PLC ±					
4 PLC ±					
ANGLES ±					
MATERIAL		WEIGHT		RESTRICTED TO	
		CUSTOMER DRAWING		A3	
		SCALE		SHEET 1 OF 2	
				REV A1	

THIS DRAWING IS UNPUBLISHED.		RELEASED FOR PUBLICATION		20
(C) COPYRIGHT 20 BY TYCO ELECTRONICS CORPORATION. ALL RIGHTS RESERVED.				
PART NUMBER	REV	TERMINATOR	FEED TYPE	DESCRIPTION
1528933-1	A	LEADMAKER	MECH POST FEED	CUTS CARRIER
1528933-2	A	BENCH	MECH PRE FEED	CUTS CARRIER
1528933-6	A	LEADMAKER	MECH POST FEED	CONTINUOUS CARRIER
7-1528933-1	A	LEADMAKER	MECH POST FEED	-1 AND SPARE PARTS
7-1528933-2	A	BENCH	MECH PRE FEED	-2 AND SPARE PARTS
7-1528933-6	A	LEADMAKER	MECH POST FEED	-6 AND SPARE PARTS
7-1528933-7	A	-	-	SPARE PARTS KIT

⚠ RECOMMENDED SPARE PARTS.

2. GREASE RAM, CAM, CAM FOLLOWER AND FEED ROD LIGHTLY

③ CERTAIN TERMINALS REQUIRE LUBRICATION. REFER TO THE APPLICATOR INSTRUCTION SHEET FOR MORE INFORMATION.

4. LUBRICATE DAILY PER THE APPLICATOR INSTRUCTION SHEET SUPPLIED WITH THE APPLICATOR.


5 ALL CRIMP DATA SUPPLIED BY THE TERMINAL MANUFACTURER.

6 FEED MAY REQUIRE ADJUSTMENT WHEN CHANGING FROM ONE TERMINAL TO ANOTHER.

 WIRE & INSULATION RANGE SHOWN IS THAT OF THE TERMINAL

 8 CUT TO LENGTH AT ASSEMBLY.

* WARNING
ON INSTALLATION, SET WIRE
DISC TO LARGEST WIRE SIZE
SETTING. USE OF SETTINGS
BELOW MIN. REQUIRED CRIMP
HEIGHT SETTING WILL CAUSE
DAMAGE TO CRIMP TOOLING.



-	-	-	-	-	-	-	-	-	84
-	-	-	-	-	-	-	-	-	83
-	-	-	-	-	-	-	-	-	82
-	-	-	-	-	-	-	-	-	81
-	-	-	-	-	-	-	-	-	80
-	-	-	-	-	-	-	-	-	79
-	-	-	-	-	-	-	-	-	78
-	-	-	-	-	-	-	-	-	77
-	-	-	-	-	-	-	-	-	76
-	-	-	-	-	-	-	-	-	75
-	-	-	-	-	-	-	-	-	74
-77	-76	-72	-71	-6	-2	-1	PART NO	DESCRIPTION	ITEM NO

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[TE Connectivity:](#)

[1528933-2](#)