


Static Control Bag Storage





SCS Static Control Bags do not have a set life span. For best results, bag inventory should be continually replenished. We recommended that bags be stored in their original packaging. The user must determine the suitability of a static control bag for use in his particular application. Bags should be stored in a dry, well ventilated room with a reasonably consistent temperature of 76°F (24°C) and be protected from exposure to direct sunlight. Bags should not be stored in ultraviolet sunlight, moisture, or heat because the aluminum shielding layer could oxidize if exposed to these conditions. Mishandling or improper storage may render a static control bag unable to perform its function. Static control bags that are ripped, torn, or scratched should be discarded. SCS, Desco Industries Inc., recommends those who are tracking the useful life of product use the shipping/invoice date as a reference. Desco Industries Inc. expressly warrants that for a period of one (1) year from the date of purchase, SCS static control bags will be free of defects in material (parts) and workmanship (labor).


See details of Warranty, Limitation of Liability and Remedies online at SCS terms and conditions which states in part, "This product will be free from defects in material and manufacture for one year from the time of purchase. SCS MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. If this product is defective within the warranty period stated above, your exclusive remedy shall be, at the option of SCS, to replace or repair the SCS product or refund the purchase price of the SCS product. Except where prohibited by law, SCS will not be liable for any indirect, special, incidental or consequential loss or damage arising from this SCS product, regardless of the legal theory asserted."



SCS - 926 JR Industrial Drive, Sanford, NC 27332 • (919) 718-0000 • Website: StaticControl.com

Finding the manufacturing date of your bags

1. Box label - located on the outside of the box



Date is shown in the bottom right of the label in the following format: yyyy-mm-dd.

2. Case stamp - located on the outside of the box next to the box label

ZZMMYRRR-00

ZZ = machine

MM = month

= last digit of year

RRR = sequential roll on machine ZZ

Anything after the dashes = operator code

3. Lot Number




14 digit lot number is made up of:

SS = stamp serial number

= last digit of year

M = month



SCS - 926 JR Industrial Drive, Sanford, NC 27332 • (919) 718-0000 • Website: StaticControl.com

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Desco:

<u>10057 1001212 150812 150Z35 150Z46 150Z610 150Z810 10024 30023 100610 300430 1002024 3001014 30046 3001824 3001518 300610 30058 100810 300424 10058 300630 100424 3001030 1001012 1002424 10026 10044 100710 10088 30044 300510 30088 1001824 10048 1300614 13001824</u>

SCS:

30035 1001214 1501024 1501418 1501518 1501824 150610 150630 150715 150912 150Z1012 150Z1218
150Z58 150Z68 10035 3001012 100812 300812 300810 3001818 1001418 10046 3001218 1001218 1001014
1001024 1001026 1001030 1001114 1001115 1001224 1001230 1001416 1001420 1001618 1001624
1002224 1002430 1003024 100426 100510 1006.516 100612 100614 100616 100618 100624 100626 100630
100711 100716 100814 100818 15035 3001010 3001024 3001115 3001418 3001624 3002024 3002424
30033 30048 300624 30068 300715 300912 1001225 1001630 1001820 1001830 1002436 10056 10069
100715 100830 15046 15058 15068 1006.51 2126R 48X125 2126R 24X125 150810 1300912 13001024
130068 130057 130058