

00779	CUSTOMER AND ASSEMBLY DRAWING	—
-------	-------------------------------	---

QTY REQD PER ASSY		PARTS LIST	
-------------------	--	------------	--

00779	CUSTOMER AND ASSEMBLY DRAWING	—
-------	-------------------------------	---

--	--

- 1 RECOMMENDED SPARE PARTS.
- 2 GREASE LIGHTLY.
- 3 GUARD MUST BE IN PLACE WHEN OPERATING APPLICATOR IN A BENCH MACHINE.
- 4 SEE DRAWING FOR COMPONENTS

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[TE Connectivity:](#)

[1385602-1](#)