

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: [0026482093](#)
Status: **Active**
Description: 156 KK Bkwy Hdr Polz SqP SAu 9Ckt
Replacement Part Number: <http://www.molex.com/molex/products/listview.jsp?channel=Products&sType=p&query=002648209526-48-2095> see comments

Documents:

[Drawing \(PDF\)](#) [RoHS Certificate of Compliance \(PDF\)](#)
[Product Specification PS-08-50-001 \(PDF\)](#)

Agency Certification

CSA LR19980
UL E29179

General

Product Family PCB Headers
Series [41681](#)
Application Tooling Part Link 11-20-0901
Comments Original part has polarizing backwall, replacement has friction lock backwall, same dimensions and plating
Replacement Part Number [26-48-2095](#) see comments
UPC 800754903301

Physical

Flammability 94V-0
Net Weight 3.726/g

Solder Process Data


Duration at Max. Process Temperature (seconds) 005
Lead-freeProcess Capability WAVE
Max. Cycles at Max. Process Temperature 001
Process Temperature max. C 235

Material Info

Engineering Number A-41681-B9A241

Reference - Drawing Numbers

Product Specification PS-08-50-001
Sales Drawing SD-41681-001, SD-41681-001-002



Series image - Reference only

EU ELV

Not Relevant

EU RoHS

Compliant

China RoHS

REACH SVHC

Not Contained Per -
ED/61/2018 (27 June
2018)

Halogen-Free

Status

Not Low-Halogen

For more information, please visit [Contact US](#)

China ROHS	Green Image
ELV	Not Relevant
RoHS Phthalates	Not Contained

Search Parts in this Series

[41681](#) Series

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[Molex:](#)

[26-48-2093](#)