

This document was generated on 02/20/2018 PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number:0622017800Status:ActiveDescription:BMTP Repair Fixture

Documents:

RoHS Certificate of Compliance (PDF)

General


Product Family Series Comments Function Geographic Area Level of Automation More Detailed Tech Information Product Name Tool Type UPC Warranty Disclaimer

Material Info

Reference - Drawing Numbers Application Tooling Documents

Application Tooling 207123 See Tooling Specification (PDF) Above **Repair Fixture** Global Manual applicationtooling@molex.com BMTP **Press-Fit Extraction Tool** 800753277892 CAUTION: Molex tooling crimp specifications are valid only when used with Molex terminals and tooling manufactured by Molex and sold by Molex or authorized distributors ("Molex Tooling"). When using tooling other than Molex Tooling with Molex specific connector systems listed in our ATS documents, the Molex tooling qualification does not apply and the responsibility for full qualification of the connector system is that of the customer. Molex accepts no liability for connector performance or tooling support where tooling other than Molex Tooling is used or where Molex Tooling is modified.

ATS-622017800



Use With 106186 BMTP Backplane

This document was generated on 02/20/2018 PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Molex: 62201-7800