



1. RECOMMENDED SPARE PARTS.
2. GREASE RAM, CAM, CAM FOLLOWER AND FEED ROD LIGHTLY.
3. LUBRICATE DAILY PER THE APPLICATOR INSTRUCTION SHEET SUPPLIED WITH THE APPLICATOR.



		D	ECR-06-029509	TM	DEC06
		C	0150-0755-03	CMR	JUL07
		B	0150-0079-03	RK	JAN07
		A	SEE ECN 015A-0512-00	MC	NOV06
P	F	LTR	REVISION RECORD	APP	DATE

		DIMENSIONS: mm (INCHES)		MATL		HT TR		FIN	
		DO NOT SCALE PRINT.		-		-		-	
		TOLERANCES UNLESS OTHERWISE SPECIFIED:		DR 120CT00		APP 120CT00			
		1 PLC DEC ± 0.5 (0.02 IN)		M CLIFFORD		F BACKHURST			
TM	DEC06	2 PLC DEC \pm		CHK 08-11-00		REL 08-11-00		 AMP Incorporated Harrisburg, PA 17105-3608	
CMR	JUL03	3 PLC DEC \pm		L LOTHOUSE		M CLIFFORD			
CRJ	JAN03	ANGLE \pm		NAME					
MC	NOV00	SURF TEXTURE: \checkmark		SIDE FEED HD-I APPLICATOR					
APC	DATE	REMOVE BURRS, BREAK SHARP EDGES R0.38 MAX		SCALE -		D D		DNG NO 1426095	
		CASE CODE 00079		CUSTOMER AND ASSEMBLY DRAWING					
				RESTRICTED TO -					

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[TE Connectivity:](#)

[1426095-6](#)